

Privileged and Confidential
Prepared at the Request of Consul
Alaska Pacific Powder Site
Mark Johns
December 20, 1994

The following information pertains to photographs taken by Mark Johns while on a site visit to Pacific Powder Site on December 20, 1994. The text is annotated with references specific items detailed in the letter dated August 5, 1994, from Mark Johns to Mr. James Ragen.

Photo No.	Description
(1)	Site of old trailer near entrance to site, trash.
(2)	Site of old trailer near entrance to site, well house.
(3)	Pit located on first right turn, dirt road to pit with logs. Area just west of Culvert yard, under power lines, old dump with wood debris and area that looks like an old bunker.
(4, 5, 6)	Back of Culvert yard looking toward road.
(7)	Inside dipping plant, no additional work has been performed.
(8)	Corrugated garage south of dipping plant with electrical boxes.
(9)	Oil sheen on main garage floor.
(10)	Main work garage - empty shop.
(11)	Main work garage - electrical boxes.
(12)	Main work garage - electrical boxes.
(13) <i>East</i>	West side of culvert yard, visqueen pile, oily sheen.
(14)	Green abandoned car on road leading south from culvert yard. Left-hand turn to smaller road in forest. Oregon NYY 619 Tag 0094575 April 90 Green Plymouth Duster
(15)	Tank cradle, 6' diameter in forest near abandoned car.
(16/17)	Green (water?) pipe 3" and valve underground near abandoned car.
(18)	Second tank cradle 5' near abandoned car.
(19/20)	Block building in woods, white electrical pipes.
(21)	Quonset hut, 1/2 buried, double locks .
(22)	Block building.
(23)	Green cinder block 8' x 8' double locks w/tank cradle.
(24)	Block house sump, new excavation, building 2012. Block house cleaned but smells like diesel (#16/17 on August list).
(25)	Block house oil water separator (#15 on August list) Pit w/PVC drain (4").
(26)	Small diesel tank still remains (#2 on August list).

Privileged and Confidential
Prepared at the Request of Consul
Alaska Pacific Powder Site
Mark Johns
December 20, 1994

Photo No.	Description
(27/28/29)	Waste oil tank at diesel shop has been removed, more soil excavated, visibly contaminated, sheen.
(30)	Surface sump pipe removed, hole open.
(31/32/33)	Drain or oil pit behind diesel shop, large pit filling with water.
(34)	Red heating oil tank behind diesel shop.
(35/36)	Heating oil (diesel) tank at truck stop (#2 on August list). I stirred soil along 3/8" diameter tubing run - oil sheen.
(37/38/39)	Additional work: pipes removed but still laying about. No sheen. Electrical box area: no transformers present (#5 on August list) - transformers (#6 on August list).
(40)	Tank Farm area. All tanks removed; cement slab still in place. Some above ground piping still remains (#7 on August list).
(41)	Main plant fuel tank foot print.
(42/43)	Same as before (#8 on August list) drain field behind main production building.
(44)	Sump at scale house. Scale has been removed.
(45)	Area to east of Main Plant (#12 on August list).
(46)	Main Plant inside sump.
(47)	Main Plant general interior. Floors look clean (#10 on August list) with a slight smell of diesel.
(48)	Inside main plant.
(49)	Second main plant sump covered with plywood.
(50)	Bag house empty but still has some oil stains (#13 on August list). Building 9310 yellow wood siding cleaned out (#13 on August list).
(51)	Sump to east of Main Plant, open ground corrugated 3'
(52)	Area behind powder office (#14 on August list) lots of water. Looks same as before.
(53)	Burn pit at main dump (#18 on August list). Looks the same.
(54)	Mean Plant area (#19 on August list).
(55)	Mean Plant concrete.
(56/57/58/59/60)	Panorama from top of soil pile at Mean Plant. Building 9023 under block east of mean plant empty.
(61)	Magazine #1 (#20 on August list) cleaned.
(62)	Seismic pond (#22 on August list).
(63/64/65/66)	Panorama seismic pond. Looks the same.
(67/68)	Farm house burn pit (# 21 on August list). Same as before.



3



4



1



2



5



6



7


Dec 20 1994 #1 of 2



8

Passive Poodet

12



11



10



9

